B-LAYER/THERMAL BARRIER INTEGRATION

SEPTEMBER 21, 1999

MECHANICS SESSION

E. ANDERSSEN, LBNL

REMINDERS


- PROPOSAL TO PUT PERMANENT RAILS IN DETECTOR
 - RAMIFICATIONS
 - PROGRESS/AREAS FOR IMPROVEMENT
- HISTORY OF THERMAL BARRIER
 - GENERAL PROBLEM
 - KNOWN TROUBLE WITH OLD SOLUTIONS
 - PROPOSED INTEGRATED SOLUTION



B-LAYER INSTALLATION

- UPDATES ON WORK IN PROGRESS
- REQUIREMENTS/NECESSITY
 - LOOKING AT BEAMPIPE DESIGN WHICH DOES NOT REQUIRE B-LAYER REMOVAL FOR MAINTENANCE
 - FINITE DETECTOR LIFE-STILL A NECESSITY
- Access
 - SHORT OPENING SCENARIO LITTLE CHANGED
- Constraints
 - SPACE LIMITS-DURING ACCESS REMAIN THE SAME
 - ALIGNMENT GRID INCREASED
 - THERMAL BARRIER IN FORWARD SCT WILL ALLOW US TO SUPPORT SERVICES AND A RAIL





- PROPOSED TO MOUNT RAIL OFF OF FRAME END STIFFENER AND BARREL SUPPORT CONES
- SERVICES OUT ONE SIDE
- RAIL IN SCT FORWARD-ALSO PERMANENT
- SUPPORT OF SERVICES OFF OF SCT FORWARD THERMAL BARRIER (VIA RAIL)
- TRY TO INTEGRATE B-LAYER INSTALLATION WITH B-LAYER SUPPORT



RAMIFICATION OF PROPOSAL

- SIMPLIFIES ASSEMBLY OF B-LAYER, ARGUABLY, MAKES POSSIBLE...
- INCREASED SERVICES ON ONE SIDE OF DETECTOR AND IN CENTER SECTION
- REQUIRES TIGHTER INTEGRATION WITH SCT FORWARD
- NEGLECTED THERMAL BARRIER PENETRATIONS




THERMAL BARRIER REQUIREMENTS

- THE VOLUME FOR INSTALLING THE B-LAYER IS FILLED WITH CAVERN AIR - DEWPOINT OF 13 DEG C
- DETECTOR VOLUME IS AS LOW AS -15 DEG C+ THERMAL BARRIER MUST STAND-OFF ~30 DEG C THERMAL GRADIENT IN MINIMAL SPACE
- STRUCTURE OF THERMAL BARRIER MINIMIZED FOR XO
- No Condensation is allowed on any surface within the detector
- DESIGN REQUIRES KNOWLEDGE OF INSTALLATION AND REMOVAL SCENARIOS, TIMES AND FAILURE MODES

THESE REQUIREMENTS LEAD TO AN ACTIVE THERMAL BARRIER REQUIRING HEAT INPUT ON THE EXTERIOR SURFACES TO MEET BOUNDARY CONDITIONS



PIXEL DETECTOR



SEPTEMBER 99 MECHANICS PIXEL DETECTOR INTEGRATION

THERMAL BARRIER CONSTRUCTION

TEST ARTWORK FOR CURRENT LIMIT TESTING. LEFT SETS HAVE EQUIVALENT RADIATION LENGTHS. SLIGHTLY MORE HEAT IS REQUIRED AT PENETRATIONS AND BOUNDARIES


TEST PROGRAM ON:

DOUBLE-SIDED AL-KAPTON
20MICRON AL
50MICRON KAPTON

HEATER PATTERNS ETCHED IN ONE SIDE


DESIGN GOAL:

1-AMP / TRACE
2 TRACES / SQUARE CM
(TRACES HAVE 5MM PITCH)





HEAT LEAKS/PENETRATIONS




NOTE: THIS IS AN EXTREMELY OLD ILLUSTRATION. IT IS USED TO HERE ONLY TO ILLUSTRATE A PROBLEM

IT IS NECESSARY TO SEAL AT EVERY PENETRATION. WHERE THERE IS A PENETRATION IT REQUIRED A RING TO SEAL THE CYLINDERS TO.

AT EVERY SEAL IT IS NECESSARY TO GUARANTEE THAT NO COLD GAS LEAKS AS WELL AS PROVIDING NO THERMALLY CONDUCTIVE PATH.



Nominal "Base-Line" Design



- THERMAL BARRIER IN THREE PARTS (CENTRAL + 2FORWARD)
- TIED SUPPORT FINGERS
 TOGETHER WITH
 INSULATOR/SEAL
- POTENTIAL FOR LEAKS NEXT TO BEAMPIPE AND B-LAYER
- NEEDS STRUCTURALLY DE-COUPLING SEALS


ADDITIONAL PROPOSAL



- INTEGRATE SUPPORT RAIL INTO THERMAL BARRIER-SOLVES PROBLEM OF THERMAL PENETRATIONS/INTERFACING
- SUPPORT THERMAL BARRIER
 FROM FRAME STIFFENER
- Make Frame Stiffener Inner
 Wall of Thermal Barrier
- PROVIDE TIE POINTS FROM SUPPORT CONE TO EXTERIOR OF THERMAL BARRIER TO LOCATE B-LAYER
- PROVIDE INTERFACE TO REMAINDER OF BARREL THERMAL BARRIER




CHANGE OF SUPPORT



- RECOMMEND CHANGING B-LAYER SUPPORT TO VERTICAL PLANE
- HANG FROM UPPER RAIL, GET ORIENTATION FROM LOWER RAIL
- FINGERS BENEFIT IN Z-STIFFNESS FROM Z-STIFFNESS OF ENDPLATES
- RAIL BENEFITS FROM BENDING STIFFNESS OF THERMAL BARRIER
- SIMPLIFIES INTERFACE BY **AVOIDING PENETRATIONS**




DETAIL OF BARREL TB INTERFACE





PRECISE PARTS



- ENDCAP OF BARREL TB IS
 TRAPPED ONLY IN Z, RADIAL
 MOTION IS ALLOWED
- INTEGRATION OF THERMAL
 BARRIER WITH SUPPORT
 ALLOWS FOR MORE WELL
 DEFINED INTERFACE WITH
 EXTERNAL THERMAL BARRIER
- DUE TO SPACE CONSTRAINTS
 AND INTERFACES/SEALS,
 THERMAL BARRIERS WERE
 NECESSARILY ACCURATE
 STRUCTURES



DISCUSSION

- Sources of Error
- Z-STIFFNESS
- PRESSURE VARIATION
- ASSEMBLY TOOLING NOT INCLUDED

